

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School :

St. Jude Public School, Kuttanellur

1. Name of the Officer

: Divya Gopinathan

2. Location

: Thrissur, Ollur

3. Period for which the certificate is issued

: 2024-25

4. Types of building

5. Nature of defect if any

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks if any)

} NIL

6. Any Major defects notices which will render the building unsafe in any manner

: NIL

7. Whether maintenance works have been done properly

: YES

8. Whether the structure is sound or not for conducting classes

: Sound under normal weather condition

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 14/06/2024
and found to be fit / unfit to conduct classes for the period 2024-25
for the reason stated above.

Place: Ollur

Date: 14/06/2024



4/7/24
DIVYA GOPINATHAN
Assistant Engineer
ASSISTANT ENGINEER LSGD
THRISSUR CORPORATION

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

Name of the School : ST. JUDE PUBLIC SCHOOL, KUTTANELLUR

1. Name of the Officer : SHAILAJA P.K.
2. Location : KUTTANELLUR, OLLUR
3. Period for which the certificate is issued : 24-25
4. Types of building : R.C.C. BUILDING
5. Nature of defect if any :
 - a) Foundation and basement : NIL
 - b) Superstructure : NIL
 - c) Doors and windows : NIL
 - d) Wood work wrought and put up : NIL
 - e) Roof : NIL
 - f) Flooring : NIL
 - g) Miscellaneous (Cracks if any) : NIL
6. Any Major defects notices which will render the building unsafe in any manner : NO
7. Whether maintenance works have been done properly : NEW BUILDING
8. Whether the structure is sound or not for conducting classes : SOUND UNDER NORMAL WEATHER CONDITLON

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on ... 20/07/2024
and found to be fit / ~~unfit~~ to conduct classes for the period ... 2024-25
for the reason stated above.

Place: ... OLLUR

Date: ... 20/07/2024



Shailaja
SHAILAJA P.K.
ASSISTANT EXECUTIVE ENGINEER (PEN-485942)
LID & EW
Assistant Engineer
THRISSUR CORPORATION