

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. 272/23

Date : 20/07/2023

It is certified that an inspection team headed by REGI BANARGY
HEALTH INSPECTOR (Name of Officers
with designation) from HEALTH SERVICE CHC OLLUR (Name of
Department/Office) inspected the ST. JUDE PUBLIC SCHOOL
ELAMTHURUTHY, KUTTANELLUR, THRISSUR - 14 (Name & Address of
the School) on 20/07/2023 and found that the ST. JUDE PUBLIC
SCHOOL, KUTTANELLUR (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.

The above valid for a period of One year



Signature with Seal : *Regi Banargy*

Name :

REGI BANARGY

Designation :

HEALTH INSPECTOR
Community Health Centre, Ollur

To

THE PRINCIPAL

ST-JUDE PUBLIC SCHOOL

KUTTANELLUR

(Name & Address of the Institution)



Ubic Envirocare Lab

TEMBLE TREES, GROUND FLOOR, ROOM NO.9, PAZHAYANADAKKAVU ROAD, THRISSUR-680001

Ph. 0487 2997288, Mob: 9037555789 E-mail - ubicenvirocare@yahoo.com

State Pollution Control Board Approval No. PCB/CL/RL/48/2021

ANALYSIS REPORT

Sample no : - UL/01539
Sample name : - Well Water Sample
Sample submitted by : -The Party
Standard referred by : -IS:10500:2012

Sample Receipt : - 23.06.2023

Date of Issue : - 30.06.2023

PCB Approval No. : - PCB/CL/RL/48/2021

To
ST. JUDE PUBLIC SCHOOL
KUTTANELLUR
THRISSUR

Sl. No	Parameters tested	Unit	Method of Test	Results	Acceptable Limit as per IS:10500-2012
--------	-------------------	------	----------------	---------	---------------------------------------

PHYSICAL EXAMINATION

1.	Colour	Hazens	IS:3025(4)—1983(R.2017)	3	5
2.	Taste & Odour	--	IS:3025(5)—2018	Agreeable	Agreeable
3.	Turbidity	NTU	IS:3025(10)—1984-R.2017)	0.4	1 NTU
4.	Electrical Conductivity	µs/cm	IS:3025(14) –1984	143µs/cm	---
5.	Total Dissolved Solids	Mg/l	IS:3025(16) –1984(R.2017)	86	500 Mg/l

CHEMICAL EXAMINATION

6.	Ph	pH unit	IS:3025(11) –1983(R.2017)	7	6.5 – 8.5
7.	Iron(as Fe)	Mg/l	IS:3025(53) –2003(R.2014)	0.13	1.0 Mg/l
8.	Total Alkalinity(asCaCO ₃)	Mg/l	IS:3025(23) –1986(R.2019)	12	200 Mg/l
9.	Chloride(as Cl)	Mg/l	IS:3025(32) –1988(R.2019)	8.2	250 Mg/l
10.	Residual chlorine	Mg/l	IS:3025(26) –1986(R.2019)	Nil	0.2 Mg/l
11.	Acidity	Mg/l	IS:3025(22) –1986(R.2019)	Nil	---
12.	Total Hardness(asCaCO ₃)	Mg/l	IS:3025(21) –2009(R.2019)	17.2	200 Mg/l
13.	Calcium(as Ca)	Mg/l	IS:3025(40) –1991(R.2019)	3.6	75 Mg/l
14.	Magnesium(asMg)	Mg/l	IS:3025(46) –1994(R.2019)	2.1	30 Mg/l
15.	Sulphate(as SO ₄)	Mg/l	IS:3025(24) –1986(R.1992)	3.23	200 Mg/l
16.	Nitrate (as NO ₂)	Mg/l	IS:3025(34) –1988(R.2003)	1.01	45 Mg/l

BACTERIOLOGICAL ANALYSIS -MPN Method

17.	No. of E.coli/100ml	IS:1622--1996	Absent/100ml	Shall not detectable in any 100ml sample
18.	Coliforms		Absent/100ml	

REMARKS: Tested parameters are within the standards.

CHEMIST



APPROVED BY KERALA STATE POLLUTION CONTROL BOARD