

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. 07/2025Date : 02/07/2025

It is certified that an inspection team headed by Abha Gopinath
Health Inspector (Name of Officers
with designation) from Kerala State Health Services (Name of
Department/Office) inspected the St. Jude Public School
Kuttanellur, Kuttanellur, Thrissur, 680014 (Name & Address of
the School) on 23/07/25 and found that the St. Jude Public
School, Thrissur - 680014 (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.

The above valid for a period of One YearSignature with Seal : Abha

Name :

Abha Gopinath

Designation :

Health Inspector

To

The Principal
St. Jude Public School
Thrissur - 680014

(Name & Address of the Institution)

HEALTH INSPECTOR
Community Health Centre, Ollur

libby
MANAGER
ST. JUDE PUBLIC SCHOOL
KUTTANELLUR P.O., THRISUR - 680 014

4

Philip
PRINCIPAL
ST. JUDE PUBLIC SCHOOL
KUTTANELLUR P.O., THRISUR-680 014





Ubic Envirocare Lab

TEMPLE TREES, GROUND FLOOR, ROOM NO.9, PAZHAYANADAKKAVU ROAD, THRISSUR-680001
Ph. 0487 2997288, Mob: 9037555789 E-mail - ubicenvirocare@yahoo.com
State Pollution Control Board Approval No. PCB/CL/RL/48/2023

ANALYSIS REPORT

Sample no : - UL/01649
Sample name : - Well Water
Sample Submitted by : - C/o Aqua world
PCB Approval No. : - PCB/CL/RL/48/2023
Standard referred by:-IS: 10500:2012

Sample Receipt : - 09.06.2025
Date of Issue : - 12.06.2025


To
ST. JUDE PUBLIC SCHOOL
KUTTANELLUR
THRISSUR

Sl. No	Parameters tested	Unit	Method of Test	Results	Acceptable Limit as per IS:10500-2012
PHYSICAL EXAMINATION					
1.	Colour	Hazens	IS:3025(4)1983(R.2017)	1	5
2.	Taste & Odour	--	IS:3025(5)2018	Agreeable	Agreeable
3.	Turbidity	NTU	IS:3025(10)1984(R.2017)	0.6	1 NTU
4.	Electrical Conductivity	µs/cm	IS:3025(14)1984	120µs/cm	---
5.	Total Dissolved Solids	Mg/l	IS:3025(16)1984(R.2017)7	72	500 Mg/l
CHEMICAL EXAMINATION					
6.	Ph	pH unit	IS:3025(11)1983(R.2017)	7.3	6.5 - 8.5
7.	Iron(as Fe)	Mg/l	IS:3025(53)2003(R.2014)	0.07	1 Mg/l
8.	Alkalinity	Mg/l	IS:3025(23)1986(R.2019)	35	200 Mg/l
9.	Chloride(as Cl)	Mg/l	IS:3025(32)1988(R.2019)	1.2	250 Mg/l
10.	Residual chlorine	Mg/l	IS:3025(26)1986(R.2019)	Nil	0.2 Mg/l
11.	Silica	Mg/l	IS:3025(22)1986(R.2019)	Nil	
12.	Fluoride(as F)	Mg/l	IS:3025(21)2009(R.2019)	Nil	1.0 Mg/l
13.	Acidity	Mg/l	IS:3025(11)1983(R.2017)	Nil	---
14.	Total Hardness	Mg/l	IS:3025(53)2003(R.2014)	28.1	200 Mg/l
15.	Calcium(as Ca)	Mg/l	IS:3025(40)1991(R.2019)	6.3	75 Mg/l
16.	Magnesium(as Mg)	Mg/l	IS:3025(46)1994(R.2019)	3.4	30 Mg/l
17.	Sulphate(as SO ₄)	Mg/l	IS:3025(24)1986(R.1992)	4.05	200 Mg/l
18.	Nitrate (as NO ₂)	Mg/l	IS:3025(34)1988(R.2003)	1.14	45 Mg/l
BACTERIOLOGICAL ANALYSIS -MPN Method					
19.	No. of E.coli/100ml	IS:1622-1981	Nil /100ml	Shall not detectable in any 100ml sample	
20.	Coliforms		NIL/100ml		

REMARKS: - Tested parameters are within the standards

CHEMIST

[Signature]
MANAGER



[Signature]
PRINCIPAL
ST. JUDE PUBLIC SCHOOL



ST. JUDE PUBLIC SCHOOL
KUTTANELLUR P.O., THRISSUR - 680014

APPROVED BY KERALA STATE POLLUTION CONTROL BOARD